

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022008**Date Inspected:** 17-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1500**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance(QA) Inspector Mr.Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. The QA Inspector observed and/or found the following:

BAY # 14

This QA Inspector randomly observed the following work in progress.

OBG 14EAST

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066179 performing the Shielded Metal Arc Welding process on weld 004 located at PCMK SEG3019X. ZPMC QC Mr. Guo Xing Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2214-Tc-u4b-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 068917 performing the Shielded Metal Arc Welding process on weld 337 located at PCMK SEG3019L. ZPMC QC Mr. Guo Xing Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2214-Tc-u4b-Fcm-1.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066418 performing the Shielded Metal Arc Welding process on weld 011 located at PCMK SEG3019Z. ZPMC QC Mr. Guo Xing Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-Fcm-Repair-1. Critical weld repair report identified as B-CWR2755.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 215553 performing the Shielded Metal Arc Welding process on weld 025 located at PCMK SEG3019AA. ZPMC QC Mr. Guo Xing Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-Fcm-Repair-1. Critical weld repair report identified as B-CWR2755.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 037748 performing the Shielded Metal Arc Welding process on weld 016 located at PCMK SA3364. ZPMC QC Mr. Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2114-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066733 performing the Flux Cored Arc Welding process on weld 300 located at PCMK SEG3019L. ZPMC QC Mr. Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 067656 performing the Shielded Metal Arc Welding process on weld 099 located at PCMK SEG3019X. ZPMC QC Mr. Guo Xing Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-Fcm-Repair-1. Critical Weld repair report identified as B-CWR2614.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066763 performing the Flux Cored Arc Welding process on weld 344 located at PCMK SEG3019S. ZPMC QC Mr. Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066326 performing the Shielded Metal Arc Welding process on weld 097 located at PCMK SEG3019X. ZPMC QC Mr. Guo Xing Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-Fcm-Repair-1. Critical Weld repair report identified as B-CWR2612.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 068097 performing the Shielded Metal Arc Welding process on weld 008 located at PCMK SEG3019Z. ZPMC QC Mr. Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2114-Tc-u4b-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 037932 performing the Shielded Metal Arc Welding process on weld 007 located at PCMK SEG3019Z. ZPMC QC Mr. Guo Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2114-Tc-u4b-Fcm-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer
